

COACH MODEL : C2045, T2145 and T2140 with DD13 Engines

DATE : 9/24/2012

SUBJECT : Water Pump Tensioner and Pulley Failure

If the water pump belt tensioner and/or pulleys fail on a DD 13 engine it is recommended the belt, tensioner and pulleys are replaced as an assembly. Part numbers shown are Detroit part numbers and are available at your local Detroit Allison dealership.

